



A EVOLUÇÃO É GAUSS



IGNIÇÃO

MÓDULO DE IGNIÇÃO

FOTO	CÓD. GAUSS	SUBSTITUI	APLICAÇÃO
	GA2005 Sistema Indutivo	Bosch: 9220087004, 9220087005, 9220087006, BM100, 9220087003; Magneti Marelli: MI530700	GM: Caminhões 11000, 12000, 13000, 14000, 19000, 21000, 22000, C20, C40, C60, C70, C90, Opala, Caravan 2.5, 4.1, Chevette 1.4, 1.6, Chevy 500 1.6, Ipanema, Kadett 1.8, 2.0, Marajo 1.4, 1.6, FIAT: 147 1.3, Fiorino 1.3, Elba 1.3, 1.5, Oggi 1.3, Panorama 1.3, Premio 1.3, 1.5, Spazio 1.3, Uno 1.3, 1.5, Mille 1.0; FORD: Belina/DelRey II 1.8, Escort 1.3, 1.6, 1.8, Pampa 1.6, 1.8, 1.6 4x4, Royale 1.8, 2.0, Verona 1.6, 1.8, Versailles 1.8, 2.0 VW: Apollo 1.8, Brasília 1.3, Fusca 1.3, 1.6, Gol 1.3, 1.6, 1.8, Kombi 1.6, Parati/Santana/Passat/Voyage 1.6, 1.8, 2.0
	GA2005N Sistema Indutivo	Bosch: 9220087004, 9220087005, 9220087006, BM100, 9220087003; Magneti Marelli: MI530700	GM: Caminhões 11000, 12000, 13000, 14000, 19000, 21000, 22000, C20, C40, C60, C70, C90, Opala, Caravan 2.5, 4.1, Chevette 1.4, 1.6, Chevy 500 1.6, Ipanema, Kadett 1.8, 2.0, Marajo 1.4, 1.6, FIAT: 147 1.3, Fiorino 1.3, Elba 1.3, 1.5, Oggi 1.3, Panorama 1.3, Premio 1.3, 1.5, Spazio 1.3, Uno 1.3, 1.5, Mille 1.0; FORD: Belina/DelRey II 1.8, Escort 1.3, 1.6, 1.8, Pampa 1.6, 1.8, 1.6 4x4, Royale 1.8, 2.0, Verona 1.6, 1.8, Versailles 1.8, 2.0 VW: Apollo 1.8, Brasília 1.3, Fusca 1.3, 1.6, Gol 1.3, 1.6, 1.8, Kombi 1.6, Parati/Santana/Passat/Voyage 1.6, 1.8, 2.0
	GA2013 Sistema Indutivo	Bosch: 9 220 087 011, 9 220 087 013; Magneti Marelli: MI530701; VW: 305.905.351.1	VW: Gol 1.6/ 1.8, Parati I 1.6/ 1.8, Quantum 1.8, 2.0, Santana 1.8/ 2.0, Saveiro 1.6/ 1.8 Voyage 1.6/ 1.8; LADA: Laika 1.5/ 1.6, Niva 1.5/ 1.6; MIURA: Top Sport 2.0
	GA2013N Sistema Indutivo	Bosch: 9 220 087 011, 9 220 087 013; Magneti Marelli: MI530701; VW: 305.905.351.1	VW: Gol 1.6/ 1.8, Parati I 1.6/ 1.8, Quantum 1.8, 2.0, Santana 1.8/ 2.0, Saveiro 1.6/ 1.8 Voyage 1.6/ 1.8; LADA: Laika 1.5/ 1.6, Niva 1.5/ 1.6; MIURA: Top Sport 2.0
	GA2019 Sistema Indutivo	Bosch: 9220087019; Fiat: 7075200	FIAT: Premio, Elba e Pick-up lx todos c/motor 1.6 e Uno c/motor 1.6r todos a gas. e a alc. após 01/90
	GA2026 Sistema Indutivo	Bosch: 9220087026; Fiat: 7076168	FIAT: Uno Mille, Elba, Prêmio, Uno 1.5
	GA2030 Sistema Hall	Bosch: 1227030030; Audi / VW: 867 905 352; Lucas: DAB 954; Telefunken: 339 700; Valeo: CD 877; Magneti Marelli: 940038504, 940038504010, MI530702	VW: Logus, Pointer, Apollo, Polo; FORD: Escort, Verona; IMPORTADOS: Audi 80 2.0, 1.6, Multivan, Passat 1.6, Polo, Vento
	GA2049 Sistema Hall	Audi / VW: 86790535; Bosch: 1227030049; Magneti Marelli: 940038507, 940038507010, MI530704; Valeo: CD878	FORD: Escort CHT 1.6; VW: Gol 1000, Golf, Passat, Voyage, Apollo; IMPORTADOS: VW Passat 1.6, Polo 1050, Transpoter, Vento
	GA2138 Sistema Hall	Bosch: 0221600001, 0221600006, 0221600008, 0221600011, 0227100100, 0227100011, 0227100013, 0227100014, 0227100013, 0227100016, 0227100018, 0227100017, 0227100018, 0227100019, 0227100920, 0227100921, 0227100922, 0227100923, 0227100924, 1227034, 1227000001, 1227000004, 1227022008, 1227030046; Audi / VW: 211905351A, 211905351B, 211905351D, 211905351E; Magneti Marelli: MI530705	VW: Gol, Saveiro; FIAT: Tempra 16V; IMPORTADOS: Alfa Romeo, Audi, BMW, Mercedes Benz, Opel, Porsche, Saab, Seat, Vauxhall, Volvo, VW: Daimler
	GA2140 Sistema Indutivo	Bosch: 0227100140, 1127022017, 1127022018, 1227022017, 1227022018, 1227022031, 1227062018, 1237010028, 1237010029, 1237010031, 1237010038	FORD: Escort 1.1/ 1.1 Turnier, 1.3/ 1.3 Cabrio/ 1.3 Express/ 1.3 Turnier, 1.4/ 1.4 Cabrio/ 1.4 Turnier/ 1.4 Express, 1.6/ 1.6 Cabrio/ 1.6 RS Turbo, 1.6 Turnier, 1.8D, 1.8D Turnier; Fiesta 1.0, 1.1, 1.4; Orion 1.3/ 1.3i/ 1.4/ 1.6/ 1.6i; PEUGEOT: 106 1.1/ 1.1i/ 1.4/ 1.4i; 205 1.0/ 1.1/ 1.1i/ 1.3/ 1.4/ 1.4i/ 1.4i XT/ GT/ 1.6 CTI/ 1.6 GTI/ 1.9 CTI/ 1.9 GTI; 306 1.4/ 2.0i 16V; 309 1.1/ 1.1i/ 1.4/ 1.6/ 1.6i/ 1.9; 405 1.4/ 1.6/ 1.6i/ 1.8/ 1.9/ 1.9i/ 1.9 TD/ 2.0; 405 Break; 605 2.0; Boxer 2.0; CITROËN: AX 1.0/ 1.1/ 1.1i/ 1.4/ 1.4i; BX 1.4/ 1.4i; C15E 1.1/ 1.4/ 1.4i; XM 2.0/ 2.0i; ZX 1.1/ 1.1i/ 1.4/ 1.4i

FOTO	CÓD. GAUSS	SUBSTITUI	APLICAÇÃO
	GA2142 Sistema Hall	Bosch: 0227100142, 0227100143, 0227100147; Magneti Marelli: MI530706	VW: Apollo 1.8, Fusca 1.6 >08/93 / (álc.), Gol 1.0 >1/92/1.6, Voyage/Parati/Saveiro 1.6 <92 (álc.), Gol/Parati 1.8 GTS <03/92, Gol/Voyage/Parati/Saveiro 1.8 >92, Kombi 1.6 >93 (álc.), Logus 1.6, 1.8 (álc.) >93, Santana 1.8, 2.0 >03/92; AUDI: 80 2.0 90-91; FORD: Escort 1.6, 1.8 >93, XR3 1.6, 1.8, 2.0 >9, Pampa 1.6, 2.0 2.0 (álc.), Verona 2.0 >93, Verona 1.6 / 1.8 / 2.0 / (álc.), Versailles 1.8, Royale 1.8 >01/93 / (álc.), 2.0 >03/92 (álc.)
	GA2210 Sistema controlado pela central (MCE)		AUDI: A3 1.6 99-06; VW: Fox 1.0, 1.4, 1.6 Total Flex 03>, Polo/ Sedan, Total Flex 04>, Gol III, IV, V 1.0 Mi, 1.0 Turbo, 1.6, 05>, Kombi 1.4 Total Flex 06>, Golf IV 1.6 06-08, Parati 1.0 Mi 16V
	GA2379 Sistema Indutivo	Delco: 16139379, 1989747, D1960A, D1980, DM 1980, PRD00165; Magneti Marelli: MI530707	GM: Kadett 92/96, Monza 92/96, Ipanema; IMPORTADOS: Buick, Chevrolet, GM-Trucks, Oldsmobile, Pontiac
	GA2906 Sistema Indutivo	Delco: D1906, DM 1906; Magneti Marelli: MI530708	GM; ALFA ROMEO; AUTOBIANCHI; FSO; FIAT; LANCIA; LEYLAND; PEUGEOT; RENAULT; ROVER; SEAT; FERRARI
	GA2961 Sistema Indutivo	Delco: 13010892, 16010892, 196140049, 1977958, 1979107, 1979571, 6237754, D1957, D1958, D1961	GM: Ascona C 1.6i 1.6; Astra 1.6i 1.6 Mot. C16NZ; Corsa A 1.3i 1.3; Corsa A 1.6 GSi; Kadett E 1.3i; Kadett E 1.6i; Vectra 1.6i C16NZ, E16N; HONDA: Civic, CRXi 4-Cylinder Exc; VAUXHALL: Astra, Belmont 1.3i; Astra, Belmont 1.6i; Cavalier 1.6i
	GA2401	Ford: F4FF-12A297-AA, 86FB-12A297-AA; VW: 377.907.401	FORD: Pampa 1985>1997, Versailles 1991>1996 (com injeção eletrônica); VW: Gol CHT 1000 1992>1996, Gol 1.6 1981->, Gol 1.8 1985->, Gol 2.0 1989-> (com injeção eletrônica), Quantum 1985>2002, Santana 1985>2006
	GA2551 Sistema Indutivo	Bosch: 1227010014, 1227022003; Delco: 16010888; Ford: 81SF12K059AA, 81SF12K059AB	FORD: Escort 1.3 1980>2002
	GA2056 Comando do sensor de posição	Hitachi: RSB-56	NISSAN: Sunny, Hatchback, Almera, X-Terra, Pathfinder, Sentra, Quest, Frountier
	GA2118 Sistema Indutivo	Lucas: 804 28, 84 403, 84 403D, 84 453, 84 896A, 84 950A, DAB 118, DAB 127, DAB 129, DAB 135	FORD: Escort 35,55 Van 1.3 CVH; Escort 35,55 Van 1.4 CVH; Escort 55 Van 1.6 CVH; Escort Combi 1.4 CVH; Escort III 1.3 CVH; Escort III 1.4 CVH; Escort III 1.6 CVH; Fiesta 1.4; Fiesta 1.6; Fiesta XR2 CHV; Orion 1.3 CVH; Orion 1.4 CVH; Orion 1.6 CVH; RELIANT: Scimita RSS1 1.3, 1.4, 1.6; MORGAN: Four-Ford 1600 OHC
	GA2912 Sistema Hall	Lucas: 549.87.086, DAB134 34A, 84890D, DAB126, LM126; GM: 90243618, 90360314, 90360315; Opel: 1237334, 1237464; Magneti Marelli: MI530709	GM: Corsa 1.0, 1.4 EFI 94/96; IMPORTADOS: Opel, Vauxhall.
	GA2040 Sistema indutivo	Magneti Marelli: 648 330 40, BKL4A, 58170107000, XM 640, MI530703	IMPORTADOS: Fiat Duna, Panda, Uno, Lancia; FIAT: Uno, Tempra 2.0 8V 1994>

FOTO	CÓD. GAUSS	SUBSTITUI	APLICAÇÃO
	GA2064 Sistema Amplificador	Ford: DYE635, F0BZ-12A297-A, F0C66B740AA; Mazda: BP01-18-251, B3F5-18-200; Mitsubishi: J701, J790T02971; MTE-THOMSON: 7064	FORD: Escort 1.8 95, Festiva 1.3 90/93, KF Laser 1.8 90/, 90>97; KIA: 93>97; MAZDA: 89>95; MERCURY: Tracer 91>96
	GA2170 Sistema Indutivo	Mitsubishi: J170 9910A; Mazda: B541-18-V20	MAZDA
	GA2599 Sistema Hall	Delco: 10482803	GM: Blazer, S10 4.3 V6
	GA2723	Mitsubishi: J009T03471, J723T, J9T03471, MD160535	MITSUBISHI: 1992>1995, Pajero Sport, Pajero Full, L200, Triton, Mitsubishi 3000GT
	GA2852 Sistema Magnético	Mitsubishi: J152, MD607814, MD611384; Hyundai: 27120-21020, 27120-21050; Mazda: AM15-18-V20, E730-12-4910	DODGE; HYUNDAI; MITSUBISHI
	GA2853 Sistema Indutivo	Ford: E8BZ-12A297-A, DYE524; Mazda: B30318V20, 830318V20; Mitsubishi: J207; Motorcraft: DYE524; MTE-THOMSON: 7088	FORD: 88>89; MAZDA: B2200 2.2 89>93, B2600 2.6 1989, MPV 2.0 89>94, MX-3 1.6 91>94
	GA2440 Sistema Indutivo	Toyota: 89620-12440, 89620-12420, 89620-12680, 89620-16260	TOYOTA: Corolla 1.8 16V Gasol. 1992 > 2002