



FUEL INJECTION PARTS
SISTEMA DE INYECCIÓN DE COMBUSTIBLE

IDLE AIR CONTROL MOTOR
ACTUADOR DE RALENTI



GS6001

6 Pins

REPLACES / REEMPLAZA:

Fiat: 46.451.794; **Magneti Marelli:** 40415202; **Short Code:** B 20/01; **Siemens/VDO:** AT-02001R; **Bosch:** F 000 99M 001

APPLICATION / APLICACIÓN:

FIAT: Fiorino Furgão/Pick-up 1.5 (MPI) >98, Palio 1.0/1.5 (MPI - alcohol/gasoline) 96>98, Palio Weekend 1.0 (MPI - 6 marchas), 1.5 (MPI) 97>, Siena 1.0, Strada 1.5 (MPI - gasoline) 98>, Siena 1.5 (MPI - alcohol) 98>, Uno 1.0 (MPI - alcohol) 99>, Uno Furgoneta 97>98;



GS6002

4 Pins

REPLACES / REEMPLAZA:

Ford: XS4U9F715DB; **Magneti Marelli:** CA 002 BPM

APPLICATION / APLICACIÓN:

FORD: Courier 1.6, Fiesta, Ka 1.0/1.6, Fiesta 16V 1.4 (MPI - gasoline) 09/99>, EcoSport 1.6 8V (MPI - gasoline) 03>, New Fiesta 1.0 (MPI - gasoline) 02>;



GS6004

REPLACES / REEMPLAZA:

Hyundai: 35150-02600, 3515033010; **Meat & Doria:** 85034

APPLICATION / APLICACIÓN:

HYUNDAI: Atos 1.0i 1998>2003



GS6006

REPLACES / REEMPLAZA:

Fiat/ Alfa Romeo: 60576708; **Magneti Marelli:** B06/01; **Meat & Doria:** 84026

APPLICATION / APLICACIÓN:

ALFA ROMEO: 1.4/1.5/1.7 1990>1994



GS6024

4 Pins

REPLACES / REEMPLAZA:

Magneti Marelli: B24/00; **Peugeot:** 9624800480

APPLICATION / APLICACIÓN:

CITROËN: Berlingo Multispace MPV Mk1 1.4i 1996>2011, Berlingo Van Mk1 1.4i 1996>2011, Saxo Hatch 1.4 VTS 1996>2003, Xsara Hatch/Estate/Coupe 1.4i 1997>2005, ZX Hatch/Estate 1.4i 1991>1997;

PEUGEOT: 106 Mk2 Hatch 1.4i 1996>2004, 306 Hatch 1993>2001, 306 Saloon 1.4 SL 1994>2001, 306 Estate 1.4 1997>2002, Partner Mk1 MPV 1.4 1996>2015, Partner Mk1 Van 1.4 1996>2015



GS6040

3 Pins

REPLACES / REEMPLAZA:

Toyota: 22270-00040; **Denso:** 136800-1931

APPLICATION / APLICACIÓN:

PONTIAC: Vibe 2003>2006;

TOYOTA: Corolla 2002>, Matrix 2003>2006



GS6042

REPLACES / REEMPLAZA:

Renault: 7701042403; **Short Code:** B 23/00; **Siemens/VDO:** AT-02300R; **Bosch:** F 000 99M 300

APPLICATION / APLICACIÓN:

PEUGEOT: 206 1.0 8V 99>;

RENAULT: Clio, Kangoo, Twingo 1.0 8V 00>;

*All with engine D7D



GS6053

6 Pins

REPLACES / REEMPLAZA:

Hyundai: 3510333030, 3510433140, 3510435300, 3510435305; **Mitsubishi:** MD628053, MD628051

APPLICATION / APLICACIÓN:

DODGE: Raider 1989, Ram 50 1990>1991, Spirit 1992>1993, Stealth 1991>1996;

HYUNDAI: Sonata 1994>1998;

MITSUBISHI: 3000 GT 1991>1999, Diamante 1992>1996, Mighty Max 1990>1994



GS6071

6 Pins

REPLACES / REEMPLAZA:

Suzuki: 1813765D00, E9T18071; **GM:** 911174517

APPLICATION / APLICACIÓN:

CHEVROLET: Tracker 1999>2003;

GMC: Trucks 1999>2003



GS6084

2 Pins

REPLACES / REEMPLAZA:

Renault: 770870084, 7700744614

APPLICATION / APLICACIÓN:

RENAULT: Laguna 1.8 1995>2001, Laguna Grandtour Estate 1.8 1995>2001, Megane I 2.0 1996, Classic Saloon 2.0 1996, Coach Coupe 2.0 1996>2003



GS6096

4 Pins

REPLACES / REEMPLAZA:

Continental: 61296

APPLICATION / APLICACIÓN:

DFSK: C37



GS6100

REPLACES / REEMPLAZA:

Citroën/Peugeot: 1920 8X; **Short Code:** B 33/00

APPLICATION / APLICACIÓN:

CITROËN: Xsara Picasso 2.0 16V (MPI) 01>;

GS6103



REPLACES / REEMPLAZA:

Fiat: 7.077.213; **Magneti Marelli:** 40397102; **Short Code:** D 51/03; **Siemens/VDO:** AT-05103R; **Bosch:** F 000 99M 103

APPLICATION / APLICACIÓN:

FIAT: Elba, Fiorino Pick-up, Prêmio, Uno 1.6 (MPI - gasoline) 94>96, Elba, Fiorino Furgão, Pick-up, Prêmio, Uno 1.5 (MPI - alcohol) 94>96, Tempra 2.0 (MPI - gasoline) 94>99, Tempra 2.0 (MPI - alcohol) 96>99, Uno 1.0 (MPI - gasoline) 97>01;

RENAULT: Clio 1.6 8V (SPI) 97>99, R19 1.6 8V (SPI) 96>;

GS6119

6 Pins



REPLACES / REEMPLAZA:

Mitsubishi: MD628174, MD628119

APPLICATION / APLICACIÓN:

MITSUBISHI: Eclipse 2000>2004, Galant 1999>2003, Outlander 2003, Montero 2002>2004, Montero Sport 1999>2004;

CHRYSLER: Sebring 2001>2005;

DODGE: Stratus 2001>2005

GS6136

4 Pins



REPLACES / REEMPLAZA:

Magneti Marelli: B12/00; **Fiat:** 9945035

APPLICATION / APLICACIÓN:

FIAT: Cinquecento 1.1 Sporting 1994>1998, Panda Mk1 Hatch 1986>2004, Panda Van 1992>2004, Punto Mk1 Hatch 1.1/1.2 1993>1999, Punto Mk1 Convertible 1.2 1994>2000, Punto Mk1 Van 1.1 1996>2000, Seicento Hatch 1.1 1998>2010, Uno Hatch 1.0 1984>1995;

LANCIA: Y10 1.0 1987>1992, Y 1.1/1.2 1995>2003

GS6150



REPLACES / REEMPLAZA:

Fiat: 7.079.064; **Magneti Marelli:** 40430102; **Siemens/VDO:** AT-05150R; **VW:** 027.998.049-1; **Short Code:** D 51/50;

Bosch: F 000 99M 150

APPLICATION / APLICACIÓN:

FIAT: Tempra 2.0 16V (MPI - gasoline) 97>99;

SEAT: Inca 2.0 (MPFI - gasoline) 97>98;

VW: Gol, Parati, Saveiro 1.6/1.8 (Mi - alcohol) 96>, Gol, Parati, Saveiro 1.6/1.8/2.0 (Mil - gasoline) 96>, Gol, Parati 2.0 16V, GTI (gasoline) 97>, Polo Classic 1.8 (Mi - gasoline) 96>, Quantum, Santana 1.8 (Mi - alcohol) 96>, Quantum, Santana 1.8/2.0 (Mi - gasoline) 96>, Van 1.6 (Mi - gasoline) 98>

GS6174



REPLACES / REEMPLAZA:

Renault: 7701047909; **VDO:** D95174; **Meat & Doria:** 84039

APPLICATION / APLICACIÓN:

RENAULT: Clio II 1.6 1998>2005, Megane MK 1 Hatch/Classic Saloon/MK 1 Coupe 1.6i/1.6e 1996>1999, Megane Convertible/MK 1 Estate 1.6e 1999>2003, Scenic MK 1 MPV 1.6i/1.6e 1996>1999

GS6184

4 Pins



REPLACES / REEMPLAZA:

VDO: D5184

APPLICATION / APLICACIÓN:

CHERY: QQ 1.1 2011>2015;

EFFA: Hafei Zhongyi Start 2011>2014;

SUZUKI: Vitara 1991>1998

GS6187



REPLACES / REEMPLAZA:

Delphi: ICD00124; **Siemens/VDO:** AT-08187R; **GM:** 93.214.071, 96.214.071, 17.108.187, 93 277 506; **Bosch:** F00099M187

APPLICATION / APLICACIÓN:

FIAT: Palio, Strada, Weekend 1.8 (MPI - Flex) 04>;

GM: Celta 1.0 (MPFI) 01>, Celta, Corsa (VHC - Flexpower) 05>, Corsa 1.0/1.6 (MPFI) 96>, Corsa 1.8 (MPFI - Flexpower) 04>, Meriva, Montana 1.8 (MPFI - gasoline/Flexpower) 04>, Omega Suprema 2.2 (EFI) 96>

GS6200



REPLACES / REEMPLAZA:

Fiat: 9.945.635; **Magneti Marelli:** 9 244 290 500; **Siemens/VDO:** AT-01200R; **Short Code:** B 02/01; **Bosch:** F 000 99M 200

APPLICATION / APLICACIÓN:

FIAT: Brava 1.6 16V (MPI - gasoline) 00>, Palio, Siena, Strada, Weekend 1.6 16V (gasoline) 96>00, Palio, Siena 1.6 8V (gasoline) 99>00, Strada 1.6 8V (gasoline) 99>

GS6209



REPLACES / REEMPLAZA:

Delphi: ICD00004; **Magneti Marelli:** 40004502; **GM:** 17.113.209

APPLICATION / APLICACIÓN:

GM: Blazer, S10 4.3 V6 Vortec 97>01

GS6220

4 Pins



REPLACES / REEMPLAZA:

Magneti Marelli: B22/0

APPLICATION / APLICACIÓN:

PEUGEOT: 206

GS6241



REPLACES / REEMPLAZA:

Renault: 8 200 299 241; **Siemens/ VDO:** AT-02800R;
Short Code: B 28/00; **Bosch:** F 000 99M 800

APPLICATION / APLICACIÓN:

RENAULT: Clio 1.6 16V 00>, Mégane 1.6/2.0 16V, Scénic 1.6/2.0 16V 00>;

*All with engine K4M

GS6245



REPLACES / REEMPLAZA:

Magneti Marelli: 40482302, 2245H

Ford: 2S6A9F715BA, 2S6A9F715BB, 1149683

APPLICATION / APLICACIÓN:

FORD: Fiesta Mk6 Hatch 1.3 2001>2008, Ka 1.3/1.6i 1996>2008, Street Ka Convertible 1.6 2003>2005

PS.: Idle Air Control Motor + Body: GS6269

GS6262

4 Pins



REPLACES / REEMPLAZA:

Peugeot: 1920-Q8, A 95262; **Renault:** 7701204054;
Citroën: 9564463480

APPLICATION / APLICACIÓN:

CITROËN: AX HB 1986>1997;

PEUGEOT: 106 I HB 1.1 1991>1996, 205 I Convertible 1.1 1989>1994, Clio I Box 1.2 1991>1998;

RENAULT: Express Box 1.2 1991>1998, Rapid Box 1.2 1991>1998

GS6269



REPLACES / REEMPLAZA:

Ford: 2S6A9F715BA, 2S6A9F715BB, 1149683; **Meat & Doria:** 84057; **VDO:** A98102

APPLICATION / APLICACIÓN:

FORD: Fiesta Mk6 Hatch 1.3 2001>2008, Ka 1.3/1.6i 1996>2008, Street Ka Convertible 1.6 2003>2005

PS.: Only Idle Air Control Motor: GS6245

GS6273

4 Pins



REPLACES / REEMPLAZA:

Fiat: 9944470, 9949159

APPLICATION / APLICACIÓN:

FIAT: Cinquecento 0.9 1991>1999, Panda Mk1 Hatch 1980>1999, Panda Van 1986>2004, Seicento Hatch 0.9 1997>2008 **SEAT:** Marbella Hatch/Box 0.9 1987> 1993

GS6300



REPLACES / REEMPLAZA:

Citroën/ Peugeot: 1920 4X; 1920 6Q/1920 V7; **Short Code:** B 13/00

APPLICATION / APLICACIÓN:

CITROËN: Berlingo 1.8 16V, Xantia 1.8 16V (MPI) 98>, Xsara 1.8/2.0, 16V 98>;

PEUGEOT: 106 1.3/1.6 8V, 306 1.8/2.0 16V, 405, 406 1.8 16V 98>;

GS6302

plastic tip fine



REPLACES / REEMPLAZA:

Magneti Marelli: 40440302; **Short Code:** B 34/00

APPLICATION / APLICACIÓN:

VW: Polo 1.6/2.0 (Mi - gasoline) 02>, Quantum, Santana 1.8/2.0 (Mi - gasoline) 02>;

GS6372

4 Pins



REPLACES / REEMPLAZA:

Dodge: 4847372, 4874372, 53030820

APPLICATION / APLICACIÓN:

CHRYSLER: Cirrus 2000, Grand Voyager 2000, Sebring 1998, Voyager 2000>2002 **DODGE:** Caravan 1998>2002, Grand Caravan 1998>2000, Stratus 1998>2000 **PLYMOUTH:** Breeze 1998>2000, Grand Voyager 1998>2000, Voyager 1998>2000

GS6401



REPLACES / REEMPLAZA:

Citroën/Peugeot: 1920 X9, 9569691680; **Bosch:** F00099M401

APPLICATION / APLICACIÓN:

CITROËN: Berlingo 2.0, Xsara, ZX 1.8 8V, 2.0 16V (MPI) 00>, Xantia 1.8 8V, 2.0 16V >97;

PEUGEOT: 306 2.0 16V (command AMC) 93>, 405 1.8 8V, 2.0 16V (caixa comando AMC) All, 406 2.0 All;

RENAULT: Mégane, Scénic 2.0 8V (MPI), Twingo 1.0 8V 00>;

GS6460

4 Pins

REPLACES / REEMPLAZA:

GM: 17111289, 17111460, 17111461

APPLICATION / APLICACIÓN:

BUICK: Century Sedan/Coupe 1983>1987, Electra Sedan/ Coupe 1986>1987, Lesabre Sedan/Coupe 1986>1988, Regal Sedan/Coupe 1986>1987, Riviera 1986>1987, Roadmaster 1991>1993, Skyhawk 1982>1986, Skylark 1983>1988, Somerset 1985>1987;

CADILLAC: Cimarron 1983>1986, Fleetwood 1990>1993, Brougham 1990>1993;

CHEVROLET: Astro 1985>1994, Camaro 1985>1992, Caprice 1985>1993, Cavalier 1983>1986, Celebrity 1985>1986, Citation 1985, Corvette 1985>1988, El Camino 1985>1987, Fullsize Pickup 1985>1995, G Series Fullsize Van 1985>1996, Express 1985>1996, Impala 1985, Lumina APV 1990>1995, Monte Carlo 1985>1988, P Series Van 1987>1997, S10 Blazer 1985>1994, S10 Pickup 1985>1995, Suburban 1987>1995, Fullsize Blazer/Tahoe 1987>1995;

GM: Silverado 5.7/6.5 1992;

GMC: Caballero 1985>1987, Fullsize Pickup 1987>1995, G Series Fullsize Van 1985>1996, Savana 1985>1996, P Series Van 1987>1996, S15 Jimmy 1985>1994, S15 Pickup 1985>1995, Safari 1985>1994, Suburban/Fullsize Jimmy 1987>1995, Yukon 1987>1995

ISUZU: Pickup 1991>1994, Rodeo 1991>1992, Trooper 1989>1991;

OLDSMOBILE: 98/98 Regency 1985>1987, Bravada 1991>1992, Calais/Cutlass Calais 1985>1988, Ciera /Cutlass Ciera 1985>1988, Cutlass/Cutlass Supreme 1986>1987, Delta 88 1986>1988, Delta 88 Custom Cruiser 1991>1992, Firenza 1982>1986, Silhouette 1990>1994, Toronado 1989>1987;

PONTIAC: 6000 1985>1988, Acadian 1982>1986, Bonneville 1985>1988, Fiero 1985>1988, Firebird 1985>1992, Grand AM 1985>1988, Grand Prix 1985>1987, J2000 1982>1984, Optima 1988, Parisienne 1985>1986, Safari 1987>1988, Sunbird 1985>1990, Tempest 1987>1988, Trans Sport 1990>1995



GS6500

REPLACES / REEMPLAZA:

Citroën/ Peugeot: 1920AH, A96157; **Short code:** B 35/00; **Bosch:** F 000 99M 635

APPLICATION / APLICACIÓN:

PEUGEOT: 206 1.4 8V 03>;



GS6502

REPLACES / REEMPLAZA:

Fiat: 7.078.983; **Magneti Marelli:** 40396502; **Siemens/VDO:** AT-05104R; **VW:** 026.998.049.2; **Short Code:** B 51/04;

Bosch: F 000 99M 104

APPLICATION / APLICACIÓN:

FIAT: Palio, Siena 1.6 8V (SPI - gasoline) 98>99;

VW: Gol 1.0 8V (SPI - CHT - gasoline) 94>96;



GS6505

3 Pins

REPLACES / REEMPLAZA:

Bosch: 0 280 140 505; **Kia:** 0K01120660;

Hyundai: 3515022000

APPLICATION / APLICACIÓN:

VW: Carat Saloon 2.2 1985>1988, Corsar Saloon 2.2

1985>1988, Jetta II Saloon 1.8 1985>1987, Passat Saloon 2.2 1985>1988, Passat Variant Estate 2.2 1985>1988, Passat WG Estate 2.2 1985>1988, Quantum Estate 2.2 1985>1988, Santana Saloon 2.2 1985>1988;

AUDI: 100 Saloon 2.2 1984>1986, Avant Estate 2.2 1985, Wagon Estate 2.2 1985 SAAB: 9000 Turbo HB 2.0 1984>1993



GS6516

REPLACES / REEMPLAZA:

Alfa Romeo: 195321101701, 1953216081337; **Bosch:** 0 280 140 516, 0 280 140 559, 0 280 140 560; **Citroën:** 034542; **Fiat:** 60.513.207, 6.081.337, 7.766.481; **GM/Opel:** 837101, 90271799; **Peugeot:** 91 540 797, 96 008 036; **VW:** 026.906.049G, 037.906.457F

APPLICATION / APLICACIÓN:

ALFA ROMEO: 164 3.0ie 04/88>09/92, 164 2.0 V6 (Turbo) 09/92>10/98;

FIAT: Fiorino Pick-up 1.6 (MPI) 10/95>10/96, Tempra Turbo 2.0 8V (MPI) 11/94>05/98, Tipo 1.6 8V (MPI) 12/95>05/97;

GM: Astra, SW 2.0 (MPFI) 09/94>12/96, C20 01/96>12/96, Calibra 2.0 16V, Vectra CD 2.0 8V (MPFI) 10/93>03/96, Grand Blazer 4.1 (MPFI) 01/98>12/99, Omega 2.0 (MPFI) 03/93>12/95, Omega, Suprema 09/92>, Omega, Suprema CD 4.1 10/94>, Pick-up Silverado 4.1 11/96>12/01, Vectra GLS 2.0 8V (MPFI) 10/96>03/96, Vectra GSI 2.0 16V 10/93>;

RENAULT: R19 1.7i 06/89>12/95;

VW: Golf III 2.0 10/92>10/97, Golf III 2.0 (Mi) 01/94>07/98, Golf GTi 2.0 10/92>10/97, Kombi 1.6 (Mi - gasoline) 11/97>12/05, Kombi 1.6 (Mi - alcohol) 02/98>12/05



GS6521

REPLACES / REEMPLAZA:

Denso: 136800-0521, 136800-0541

APPLICATION / APLICACIÓN:

HONDA: HR-V 1.6 2004



GS6524

REPLACES / REEMPLAZA:

Delphi: ICD00125; **Siemens-VDO:** AT-59524R, AT-59603R; **Magneti Marelli:** 40001902; **Bosch:** F 000 99M 603; **GM:** 17059601

APPLICATION / APLICACIÓN:

GM: Corsa 1.0/1.4/1.6 (EFI - gasoline) 94>96;





GS6553

3 Pins

REPLACES / REEMPLAZA:

Fiat: 7789627; **Bosch:** 0 280 140 553, 0 280 140 571

APPLICATION / APLICACIÓN:

ALFA ROMEO: 145 TS HB 2.0 1995>2001, 146 TS HB 2.0 1995>2001, 155 TS Saloon 1.6/1.7 1996>1997, 155 TS Saloon 2.0 1995>1997, Spider Convertible T Spark 2.0 1995>2005;

FIAT: Bravo HGT HB 2.0 1995>1998;

KIA: Mentor HB 1.8i 1995, Mentor Saloon 1.8i 1995;

LANCIA: Kappa Saloon 2.0/2.4 1994>2001



GS6556

4 Pins

REPLACES / REEMPLAZA:

Delphi: 28222556; **Magneti Marelli:** 404.812.02, IB04/00

APPLICATION / APLICACIÓN:

RENAULT: Twingo Mk1 Hatch 1.2 1996>2007



GS6577

REPLACES / REEMPLAZA:

GM: 90 512 528; **Bosch:** 0 280 140 577; **Meat & Doria:** 85036 | Era: 556125

APPLICATION / APLICACIÓN:

OPEL: Frontera A 2.2i 1995>1998, Omega B Saloon/Estate 2.0 1994>1999, Sintra 2.2i 16v 1996>1999, Vectra B Hatch/Saloon/Estate 2.5 1995>2000



GS6595

REPLACES / REEMPLAZA:

Peugeot: 034 595; **Short Code:** B 31/00; **Siemens/VDO:** AT-03100R; **Bosch:** F 000 99M 100

APPLICATION / APLICACIÓN:

PEUGEOT: 206 1.6 8v (MPI) All;



GS6600

REPLACES / REEMPLAZA:

Bosch: F 000 99M 600; **Delphi:** ICD00126; **Siemens/VDO:** AT-59600R; **GM:** 17.059.600; **Magneti Marelli:** 40001502

APPLICATION / APLICACIÓN:

GM: Blazer, S10 2.2 (EFI - gasoline), Ipanema, Kadett, Monza 1.8/2.0 (EFI - alcohol/gasoline) 91>96;



GS6601

REPLACES / REEMPLAZA:

Bosch: 0 132 008 601; **Seat:** 048 133 031

APPLICATION / APLICACIÓN:

SEAT: Cordoba 1.8 (monoponto) All, Ibiza 1.8 (monoponto) 04/95>09/99;

VW: Golf 1.8 (monoponto) 05/95>09/99;



GS6602

REPLACES / REEMPLAZA:

Bosch: 3 437 010 524, 0 132 008 600, 0 132 008 602; **GM/Opel:** 90.531.999, 825485

APPLICATION / APLICACIÓN:

FIAT: Tipo 1.4 ie/1.6 ie, Uno 1.4 ie (Turbo) All;

GM: Astra, Astra Sedan 1.8 8V (MPFI - gasoline) 10/98>09/01, Astra, Astra Sedan 2.0 8V (MPFI - gasoline) 10/98>, Astra 2.0 16V (SFI) 02/99>03/04, Corsa 1.0i 09/96>09/00, Zafira 2.0 (MPFI) 04/01>02/04, Zafira 2.0 16V (SFI) 04/01>06/05;

PEUGEOT: 106



GS6603

4 Pins

REPLACES / REEMPLAZA:

GM: 93.227.674, 17.059.603, 17.112.023

APPLICATION / APLICACIÓN:

OPEL: Corsa A HB 1.4 1985>1993, Kadett D HB 1.6 1979>1984/D Saloon 1.6 1979>1984/D Estate 1.6 1979>1984/E Estate 1.8 1985>1991/E Box 1.8 1984>1992/E HB 1.8 1985>1991/E Saloon 1.6 1986>1991/E Cat Saloon 1.6 1986>1991;

VAUXHALL: Cavalier Mk2 Saloon 1.6 1986>1988;

CHEVROLET: Astro 1992, S10 Blazer 1992, S10 Pickup 1992;

GMC: S15 Jimmy 1992, S15 Pickup 1992, Safari 1992;

OLDSMOBILE: Bravada 1992



GS6635

4 Pins

REPLACES / REEMPLAZA:

Fiat: 9945635; **Bosch:** F 000 99M 200; **Magneti Marelli:** 9244290500; **VDO:** AT01200R

APPLICATION / APLICACIÓN:

FIAT: Brava Hatch 1.6 16V 1996>2001, Palio Weekend Estate 1.6 16V 1996>2001, Tempira Saloon/Estate 1.8 1993>1996, Tipo Hatch 1.8 1993>1995



GS6657

4 Pins

REPLACES / REEMPLAZA:

Chrysler: 5003467AA, 53030450, 53030657, 53030657AB, 53030657AC

APPLICATION / APLICACIÓN:

DODGE: B150 1992>1998, B1500 1995>1998, B250 1992>1994, B2500 1995>1998, B350 1992>1994, B3500 1995>1998, D150 Pickup 1992>1993, D250 Pickup 1992>1993, D350 Pickup 1992>1993, Dakota 1992>2003, Durango 1998>2003, Ram 1500 Pickup 1994>2003, Ram 1500 Van 1999>2003, Ram 2500 Pickup 1994>2002, Ram 2500 Van 1999>2003, Ram 3500 Pickup 1994>2002, Ram 3500 Van 1999>2003, Ramcharger 1992>2001, W150 Pickup 1992>1993, W250 Pickup 1992>1993, W350 Pickup 1992>1993;

JEEP: Grand Cherokee 1993>1998



GS6678

6 Pins

REPLACES / REEMPLAZA:

Mitsubishi: MD614678, MD614679, MD628059, MD614706

APPLICATION / APLICACIÓN:

MITSUBISHI: Diamante 1997>2004, Montero 1994>2001, Montero Sport 1997>2003



GS6680

4 Pins

REPLACES / REEMPLAZA:

Magneti Marelli: 95/00; **Peugeot:** 1920 X9

APPLICATION / APLICACIÓN:

PEUGEOT: 306 Convertible 2.0 16V 1997>2002, 405 Mk2 Saloon/Estate 1.8 1992>1996, 406 Saloon/Estate/Coupe 2.0 16V 1995>2004, 605 Saloon 2.0 16V 1994>1999, 806 MPV 2.0 16V 1998>2000, Boxer Mk2 Minibus 2.0i 1994>2002



GS6699

REPLACES / REEMPLAZA:

Renault: 7 700 273 699; **Siemens/ VDO:** AT-05177R; **Short Code:** D 51/77; **Bosch:** F 000 99M 177

APPLICATION / APLICACIÓN:

RENAULT: Clio, Kangoo 1.6 8V 00>12/09;

*All with engine K7M



GS6700

3 Pins

REPLACES / REEMPLAZA:

Hyundai: 35150-23700; **Kia:** 35150-23700; **Hitachi:** 138616, 2508616; **Meat & Doria:** 84076

APPLICATION / APLICACIÓN:

HYUNDAI: Coupe 2.0 Petrol 2001>2009, Coupe 2.0 GLS Petrol 2003>2009, Elantra 2.0 Petrol 2000>2006, Trajet 2.0 Petrol 2000>2008, Tucson 2.0 Petrol 2004>, Tucson AWD 2.0 Petrol 2004>2010;

KIA: Carens 2.0 CVVT Petrol 2004>, Cerato 2.0 Petrol 2004>2007, Sportage 2.0 i 16V Petrol 2004>, Sportage AWD 2.0 i 16V Petrol 2004>



GS6715

REPLACES / REEMPLAZA:

Cód. original: 95BF-9F715-AB/AC; **Magneti Marelli:** CA001BPM; MTE: 7464

APPLICATION / APLICACIÓN:

FORD: Courier 1.3 (MPI - gasoline) 96>08/99, Escort 1.8 16V (MPI - gasoline) 97>08/99, Fiesta, Ka 1.0/1.3 (MPI - gasoline) 96>08/99;

*endura engine



GS6776

4 Pins

REPLACES / REEMPLAZA:

Magneti Marelli: B18/00; **Fiat:** 9945776

APPLICATION / APLICACIÓN:

FIAT: Palio Hatch 1.2 1997>2002, Palio Weekend 1.2 1996>2004, Punto Mk1 Hatch 1.2 1993>1999, Strada Pickup 1.2 1999>2006



GS6801

REPLACES / REEMPLAZA:

Fiat: 7.076.356; **Ford:** F5PF9N825AA; **Magneti Marelli:** 40380202; **Siemens/ VDO:** AT-00801R; **VW:** 026.906.049.1; **Short Code:** B 08/01; **Bosch:** F 000 99M 801

APPLICATION / APLICACIÓN:

FIAT: Elba, Prêmio, Uno 1.5ie (gasoline) 92>96, Fiorino (Furgão/ Pick-up) 1.5/1.6ie (gasoline) 94>96, Tempra 2.0ie (alcohol) 94>96, Tempra 2.0 16V (MPI - gasoline) 95>96; **FORD:** Escort 1.6/1.8, Verona 1.8i (gasoline) 95>96, Versailles, Royale 1.8i (alcohol/gasoline) 95>96;

VW: Gol, Parati 1.6/1.8 (SPI - alcohol/gasoline) 94>96, Gol, Parati 2.0 16V (MPFI) 95>96, Logus, Pointer 1.6/1.8i (alcohol/ gasoline) 95>96, Quantum, Santana (SPI - alcohol/gasoline) 95>96



GS6802

plastic tip thick

REPLACES / REEMPLAZA:

Magneti Marelli: 404.391.02; **Short code:** B 34/01; **VW:** 026.906.247; **Bosch:** F 000 99M 102

APPLICATION / APLICACIÓN:

VW: Gol, Parati, Saveiro 1.6 8V (Mi - gasoline/Total flex) 03>, Parati, Saveiro 1.8/2.0 8V (Mi - gasoline) 02>;



GS6898

REPLACES / REEMPLAZA:

GM: 92061898, 4030011; **Meat & Doria:** 84062

APPLICATION / APLICACIÓN:

GM: Evenda 2.0 2005, Rezzo 2.0 2005;

DAEWOO: Evenda 2.0 2002, Leganza 2.0/2.2 1997>2004, Nubira 2.0 1997, Rezzo 2.0 2000>2004



GS6900

REPLACES / REEMPLAZA:

Magneti Marelli: 40480802; **Short code:** IB 02/00; **Bosch:** F 000 99M 500

APPLICATION / APLICACIÓN:

FIAT: Brava, Doblo, Marea, Palio, Siena 1.6 16V 01>, Strada 1.4 16V (Fire) 01>;

* Attached to butterfly body, body snap-in (TBI with integrated sensors)

GS6901



REPLACES / REEMPLAZA:

Magneti Marelli: 40442902; **Short code:** IB 01/00

APPLICATION / APLICACIÓN:

FIAT: Palio, Siena, Uno 1.0 99>, Palio, Siena, Strada 1.0, 1.3 8V/16V, 1.4 8V (Fire - gasoline/flex), Uno 1.0 8V (Fire - gasoline) 01>, Uno 1.0 8V (Fire - flex) 04>;

* Attached to butterfly body, body snap-in (TBI with integrated sensors)



GS6902

3 Pins

REPLACES / REEMPLAZA:

Honda: 15022PLCJ03, 16022PLC003; **Denso:** 136800.1902, 136200-2262

APPLICATION / APLICACIÓN:

HONDA: Civic 2001>2004

GS6903

3 Pins



REPLACES / REEMPLAZA:

Hyundai: 35150-23900; **Kia:** 9520930005

APPLICATION / APLICACIÓN:

HYUNDAI: i30 2.0 16V, Elantra 2.0 16V;

KIA: Tucson 2.0 16V



GS6904

2 Pins

REPLACES / REEMPLAZA:

Ford: 2N1U-9F715AA

APPLICATION / APLICACIÓN:

MERCURY: Monterey 2004>2007, Mountaineer 2002>2008;

FORD: Freestar 2004>2007, Explorer/Sport/Sport Trac 2002>2007

GS6905

2 Pins



REPLACES / REEMPLAZA:

Ford: 157Z-9F715AA

APPLICATION / APLICACIÓN:

FORD: Focus 2003>2007, Ranger 2001>2009, Mondeo III HB 2.0 2000>2007, Mondeo Mk III HB 2.0 2000>2007, Mondeo III Estate 2.0 2000>2007, Mondeo III Clipper Estate 2.0 2000>2007, Mondeo Mk III Estate 2.0 2000>2007



GS6906

2 Pins

REPLACES / REEMPLAZA:

Ford: 96TF9F715AB

APPLICATION / APLICACIÓN:

FORD: Explorer 1998>2000, Sport 1998>2000, Sport Trac 1998>2000;

MAZDA: Pickup 1997>2000

GS6907

2 Pins



REPLACES / REEMPLAZA:

Ford: XS6U9F715AA

APPLICATION / APLICACIÓN:

FORD: Fiesta IV HB 1.3 1995>2002, Escort VII Estate 1.3 1995>1998



GS6908

2 Pins

REPLACES / REEMPLAZA:

Ford: 938F9F715AC, 938F9F715AB

APPLICATION / APLICACIÓN:

FORD: Contour 1996, Fiesta IV HB 1.25 1995>2002, Fiesta Mk IV HB 1.4 1996>2002, Mondeo I HB 1.8 1993>1996;

MERCURY: Tracer 1998, Mystique 1998

GS6951

3 Pins



REPLACES / REEMPLAZA:

Honda: 16022-PWA-901; **Denso:** 136800-1951

APPLICATION / APLICACIÓN:

HONDA: Fit 1.4 2003>2014, Fit 1.5 2005>2014



GS6960

REPLACES / REEMPLAZA:

Delphi: ICD 00120; **GM:** 17.059.602; **Magneti Marelli:** 40002002; **Siemens/VDO:** AT-59602R

APPLICATION / APLICACIÓN:

GM: Omega, Suprema 2.2 (MPFI - gasoline) 01/94>12/98;

GS6978



REPLACES / REEMPLAZA:

Ford: 978F9F715AB; **Meat & Doria:** 85027

APPLICATION / APLICACIÓN:

FORD: Cougar 2.0 16v 1998>2001, Mondeo Mk2 hatch 1.6i/1.8i/2.0i 1996>2000, Mondeo Mk2 Saloon 1.6i/1.8i/2.0i 1996>2000, Mondeo Mk2 Estate 1.6i/1.8i/2.0i 1996>2000



GS6984

2 Pins

REPLACES / REEMPLAZA:

Ford: XS4U9F715BB; **Lucas:** FDB984

APPLICATION / APLICACIÓN:

FORD: Courier Box 1.4 1996>1999, Puma Coupe 1.7 1997, Fiesta IV HB 1.25 1995>2002, Fiesta IV 1.4 1996>2002