



INJEÇÃO

SENSOR DE ROTAÇÃO

GUIA DE ABREVIações

+	TERMINAL POSITIVO DO SENSOR	S	MALHA DE ATERRAMENTO DO CABO DO SENSOR (GROUND)
-	TERMINAL NEGATIVO DO SENSOR		

FOTO	CÓD. GAUSS	SUBSTITUI	APLICAÇÃO
	GS8000	Audi/ VW: 050906433; Valeo: 254161	AUDI: A4 1994>2001, A4 Avant 1994>2002; VW: Passat 1996>2001, Passat Variant 1997>2001
	GS8001	Hyundai: 391802B000, 391802B010; Bosch: 0 986 280 497; Valeo: 366133	HYUNDAI: Elantra sedan 1.8 GLS 2011>, HB20 1.6 Premium Confort Plus 2013>2019, i30 1.8 GLS 16V 2014>; KIA: Cerato II 1.6 16V Sport 2009>2013
	GS8003	Honda: 37500-PNA-003, 37500-PNB-003, 15503L23; Denso: 15512225	HONDA: Fit 1.4/1.5 2004>2008, New Ciivc 2.0 2006>2011, CRV 2.0 2002>2009
	GS8011	Toyota: 90919-05011; Denso: DCPS-0102	TOYOTA: Corola E11 1.6 XLI S/D 1998>2002
	GS8013	Bosch: 0.261.210.207, 0.261.210.208; VW: 06A906433K, 030906433K	VW: Gol III (Power) 1.0 16V MI 2000> Gol, Parati III 1.0 16V MI (TURBO/ASPIRATE) 04/00>02, Gol, Parati, Saveiro 1.6, 1.8 (Flex) 02>Gol II Special 1.0Mi 8V 02>05
	GS8015	Honda: 37500-PLC-015; Denso: 00601D0	Honda: Civic 1.7 2001>2005
	GS8019	NRF: 755131; Hella: 6PU 009 169-171; Bosch: 0281002426; Man Trucks: 51271200014	VW: Constellation (D 08 34 190)/(D 08 36 280) 2011>2024, 17.230 EOD (Série 12 / X12) 2006>2012, 17.230 OD (D 08 34 230) 2012>2024, Worker (D 08 34 190) 2011>2021, 17.280 OT (D 08 36 280) 2012>2024
	GS8021	Bosch: 0261210291, 0281002165; Polaris: 2411589, 2410857; Iveco: 0000099450797; Fiat: 99450797	IVECO: Stralis 380 (Cursor 13) 2005>2012, Stralis 480 (Cursor 13) 2011>2017, Stralis 400 (8210.42K)/ (Cursor 13) 2002>2021, Stralis 440 (Cursor 13) 2011>2015, Trakker (Cursor 13) 2004>2017
	GS8023	GM 24582404	GM: Onix 1.0 8V 2016>2019, Prisma 1.0 8V 2016>2023, Montana 1.4 8V 2014>2022, Cobalt 1.8 8V 2019>2022, Joy Plus 1.0 8V 2019>2021
	GS8024	Hyundai: 391802J700	HYUNDAI: Creta 2.0 16V 2021>2024

FOTO	CÓD. GAUSS	SUBSTITUI	APLICAÇÃO
	GS8025	Ford: BM56C315BB	FORD: Ka 1.0 12V 2014>2018, Ka Sedan 1.0 12V 2015>2018, Fiesta 1.0 12V 2016>2018
	GS8028	Mercedes-Benz: A0011533120	MERCEDES-BENZ: Actros (Om 460 La Bluetec 6) 2023>2024 Atego (Om 924 La Bluetec 5)/(Om 926 La Bluetec 5)/(Om 926 La Bluetec 6) 2011>2024 Accelo (Om 924 La Bluetec 5) 2012>2024
	GS8030	Toyota: 90919-05030, 90080-19013, 02960-00755; Lotus: A131E6216S	TOYOTA: Corola sedan 1.6 XLI S/D 2002>2008, Corola sedan 1.6 VVTi 2008>2011
	GS8031	Kia: 391804A400	KIA: Sorento 2.5 16V 2003>2009
	GS8032	Hyundai: 393103C600	KIA: Sorento 3.5 24V 2010>2020, Cadenza 3.5 24V 2011>2017
	GS8033	Nissan: 23731-AW410, 23731-EC00A, 23731-EC01A, 949979-033	NISSAN: Frontier Sel 2.5 Diesel, Frontier 2.5 CD SE 2008>, Frontier 2.5 4WD 2007>2012, Frontier 2.5 LE 4WD 2005>, Pathfinder 2.5 2005>2009
	GS8034	Hyundai: 3935026900	HYUNDAI: HB20 1.0 12V 2012>2019; KIA: Picanto 1.0 12V 2011>2019
	GS8047	Toyota: 90919-05047, 90919-05067	TOYOTA: Corolla, RAV4, Camry, Corona, Previa
	GS8050	Hyundai: 39310-38050; Kia: 39310-38050; Mitsubishi: J5T23071A; Volvo: 30874179; Mazda: MD 327107	HYUNDAI: Santa Fé 2.4 2001>, Sonata 1999>; Kia: Sorento, Picanto, Optima 2001>; SUZUKI: Vitara 1.6/ 2.0 1999>; GM: Tracker 1.6/ 2.0 1999>; VOLVO: S40, V40 1995>2003
	GS8076 3 PINOS	Cummins: 5594275; New Holland: 87352952, 90418076	NEW HOLLAND: Plataforma / Combine: CR9040, CR9060, CR9065, Trator / Tractor: T8010, T8020, T8030, T8040, T8050, T9010, T9020, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305, Motoniveladora / Motor Grader: 845 DHP
	GS8097 2 PINOS	Renault: 8200746497, A2C53255629	RENAULT: Sandero 1.6 2007>2015, Duster 1.6 2011>2016, Scenic 1999>2010, Kangoo 1.6 2002>2018, Megane 1.6 1997>2014

FOTO	CÓD. GAUSS	SUBSTITUI	APLICAÇÃO
	GS8099	Dodge: 5093101AA, 5179099AA, 5179099AB	DODGE: Ram 5.9 Turbo Diesel 2500 2003>2005
	GS8104	Fiat: 7762252, 7762282; Bosch: 0.261.210104; Kia: 0K9A018891; VDO: 324003030R; Hyundai: 3965042110	FIAT: Palio, Strada, Siena, Weekend 1.4, 1.6 mpi 96>02, Punto 1.4 93>99; HYUNDAI: H200 Diesel, H1 Starex 97>04; Kia: Sportage Gasoline 84>03/ Diesel 97>03
	GS8133 2 PINOS INDUTIVO	VW: 06H906433; Audi: 06H906433; Bosch: 0 986 280 496	VW: Amarok 2.0 2010>2012, CC 2.0 2012>2017, Fusca 2.0 2012>2016, Jetta 2.0 2011>2014, Passat 2.0 2009>2011, Tiguan 2.0 2008>2011, EOS 2.0 2009>2011 AUDI: A3 2.0 2008>2014, A4 2.0 2008>2015, A5 1.8 2015>2016, A5 2.0 2009>2017, Q5 2.0 2009>2012, TT 2.0 2006>2010
	GS8145	Mitsubishi: MR985145, J5T35171	MITSUBISHI: Pajero Full 3.5 V6, Pajero Sport 3.8 2004>2012, GalantÂ 3.8 2004>2009, Eclipse 3.8 V 2007>2012, rito 3.5 V6 Flex 2008>2015
	GS8150	Kia/ Hyundai: 39180-37150, 39180-37200	HYUNDAI: Santa Fé 2.7 V6 4x4 2001>2005, Sonata 2.5 V6 24V 1998>2001, Tucson 2.7 Tração integral 2004>2010; KIA: Sportage 2.7 V6 4WD 2004>2010
	GS8151	Bosch: 0 261 210 151, 0 281 002 662, 0 281 002 742; Volvo: 20513343	VOLVO: FH (motores D13) 2006>2015
	GS8161	GM: 10456161; Delphi: SS10213	GM: Omega Australiano 3.8 V6 98>
	GS8170	Mercedes Benz: 0031532828, 0031532728; Chrysler: 05080350AA, 05080352AA; Mitsubishi: MN-960274, MN-960372	Mercedes: Classe A - A160, A190, Classe C - C230, C240, C240 automatic, C280, C32AMG, C320, C320 4matic, C43AMG, Classe 500 - CL500, CL55AMG, CL600, CLK320, CLK430, Classe E - E430, E500, E55AMG, Classe ML - ML320, ML350, ML430, ML500, Classe S - S430, S500, S600, SL500, SL55amg, SL600, SLK230, SLK32amg, SLK320
	GS8171	Mitsubishi: MR560132; Denso: J5T20171	MITSUBISHI: Pajero TR4 2.0, Pajero iO 1.8, Lancer 99>07
	GS8178	Bosch: 0261210178; VW: 078906433B	AUDI: A4 2.4 Avant quattro 1998>2001 / 2.8 1998>2000 / 2.8 Avant quattro 1999>2001 / 3.0 Avant quattro Cabriolet 2001>2004, A6 2.4 Avant quattro 1997>2005 / 2.8 Avant quattro 1998>2001 / 3.0 2001>2004, TT 1.8 T Coupe quattro 2002>2006 / 1.8 T Roadster quattro 2002>2006; (Todos Gasolina); VW: Golf IV 2.0 2007>2008, New Beetle 2.0 2006>2010, Passat 2.8 1997>2005 / 2.8 Variant Syncro 1998>2000 (Todos Gasolina)
	GS8180	Peugeot: 9640316180	Peugeot: 206 1.0 16V 2001>2005

FOTO	CÓD. GAUSS	SUBSTITUI	APLICAÇÃO
	GS8200	Hyundai/ KIA: 39180-25200, 39180-25300	Hyundai: Santa Fé 2.4 GLS / 4x4 2010>2014, Sonata 2.0/2.4 2006>2015, Tucson 2010>2015, ix35 2.0 GLS / GLS 4WD 2010>; Kia: Carens 2.0 CVVT 2006>2014, Magentis 2.0 EX 2006>2010, Sportage 2.0 LX CVVT AWD 2011>, Sorento 2.4 16v 2010>2015
	GS8206 comprimento do cabo: 46cm	Magneti Marelli: 4820083010; Fiat: 4460206	FIAT: Elba CSL 4P 1.6 8V (SPI - gasolina) 94>96 / Weekend 2P/4P 1.5 8V (SPI - álcool/gasolina) 92>96, Fiorino / Furgão/ Pick-up 2P 1.0 8V (SPI - gasolina) 96 / Furgão/ Pick-up 2P 1.3 8V (SPI - gasolina) 94>95 / Furgão 2P 1.5 8V (SPI - álcool/gasolina) 94>96 / Pick-up 2P 1.5 8V (SPI - álcool/gasolina) 94>95 / Pick-up LX 2P 1.6 8V (SPI - gasolina) 94>96 / Pick-up Trekking 2P 1.5 8V (SPI - gasolina) 96 / 2P 1.5 8V (MPI - gasolina) 97>98 / MTV 2P 1.5 8V (MPI - gasolina) 97 / Pick-up Working 2P 1.5 8V (SPI - gasolina) 96, Prêmio CS 4P 1.5 8V (SPI - álcool/gasolina) 93>94 / CSL 4P 1.6 8V (SPI - gasolina) 94>96 / S 2P 1.5 8V (SPI - gasolina) 92>93 / SL 4P 1.5 8V (SPI - gasolina) 92, Uno CS 2P/4P 1.5 8V (SPI - álcool/gasolina) 93>94 / Furgoneta 2P 1.5 8V (SPI - álcool/gasolina) 94>96 / Mille City 4P 1.0 8V (SPI - gasolina) 99>00 / Eletronic 2P/4P 1.3 8V (SPI - gasolina) 93>95 / ELX 2P/4P 1.3 8V (SPI - gasolina) 94>95 / EP 2P/4P 1.0 8V (SPI - gasolina) 96 / EX 2P/4P 1.0 8V (SPI - gasolina) 98>00 / IE 2P 1.0 8V (SPI - gasolina) 94 / Smart 2P/4P 1.0 8V (SPI - gasolina) 00>01 / Smart City 4P 1.0 8V (SPI - gasolina) 00>01 / SX 2P/4P 1.0 8V (SPI - gasolina) 97>98 / SX Young 2P 1.0 8V (SPI - gasolina) 98>99, Uno S 2P 1.5 8V (SPI - álcool/gasolina) 92>94
	GS8215	VDO: 324 005 001R; Ford: 1 110 834, YS6A-6C315-AB	FORD: Courier, Fiesta, Ka 1.0/1.3 (Endura) 96>99, EcoSport, Novo Fiesta 1.6 (Zetec RoCam) 03 > 09
	GS8220	Nissan / Infiniti: 23731-1S700	NISSAN: Pathfinder 3.3 V6 4WD 1997>2002
	GS8243	GM: 55567243; Valeo: 366506	GM: Cruze Hatch Sport Lt 1.8 Flex- Automatico 2012>2016, Cruze Hatch Sport Lt 1.8 Flex- Manual 2012>2016, Cruze Hatch Sport Lt 1.8 Flex- Automatico 2012>2016, Cruze Hatch Sport Lt 1.8 Flex- Manual 2012>2016, Cruze Sedan Lt 1.8 Flex- Automatico 2012>2016, Cruze Sedan Lt 1.8 Flex- Manual 2012>2016, Cruze Sedan Lt 1.8 Flex- Automatico 2012>2016, Sonic Hatch Lt 1.6 Flex- Manual 2012>2014, Sonic Hatch Lt 1.6 Flex- Automatico 2012>2014, Sonic Hatch Lt 1.6 Flex- Manual 2012>2014, Sonic Sedan Lt 1.6 Flex- Manual 2012>2014, Sonic Sedan Lt 1.6 Flex- Automatico 2012>2014, Sonic Sedan Lt 1.6 Flex- Manual 2012>2014, Tracker Freeride 1.8 Flex- Manual 2014>2016, Tracker Ls 1.8 Flex- Manual 2014>2016, Tracker Lt 1.8 Flex- Automatico 2014>2016, Tracker Lt 1.8 Flex- Manual 2014>2016, Tracker Lt 1.8 Flex- Automatico 2014>2016, Tracker Lt 1.8 Flex- Manual 2014>2016
	GS8251 comprimento do cabo: 42cm	Bosch: 0 281 002 102; Fiat: 77662510	FIAT: Brava 1.4 12V 94 > 98, Coupé 2.0 20V 94 > 98, Marea Turbo 98 > 07, Marea Weekend ELX 4P 2.0i 20V (MPI - gasolina) 142 CV 96 > 00, Marea, Marea Weekend HLX 4P 2.0i 20V (MPI - gasolina) 142 CV 96 > 00
	GS8269	Renault: 7700101970, 7700103069A; Bosch: 0 986 280 410	RENAULT: Clio II 1.6i / 1.6i 16V 1999 / 2007 , Twingo 1.0 16V, Kangoo 1.6i 2001 > , Mégane 1.6i / 2.0 1996 / 2002, Mégane II 1.6i 16V, Scénic I / II 1.6 16V 1999 >
	GS8279	Cummins: 2872279; CNH: 84274595, 87341787	NEW HOLLAND: T8050; CASE: 2399, 2688, 2799; VW: Costalation 19-320E, 25-320E
	GS8282	Renault: 7700101970, 7700103069A; Bosch: 0 986 280 410	Mitsubishi: Pajero Sport 2.8, Pajero Full 3.2 , L200 Triton 3.2

FOTO	CÓD. GAUSS	SUBSTITUI	APLICAÇÃO
	GS8290 comprimento do cabo: 48,5cm	Magneti Marelli: 4820084010; Fiat: 5944390, 7588435, 7604582, 7646975	FIAT: Ducato TD 2.8 8V (MPI - gasolina) 00 >, Tempra 2.0 16V (MPI - gasolina) 93 > 99, Tempra 2.0 8V (SPI - gasolina) 94 >, Uno Turbo 1.4 8V (MPI - gasolina) 94
	GS8302 comprimento do cabo: 73,5cm * Sem ar condicionado	Bosch: 0 261 210 102, 0 261 210 115; Fiat: 7756925, 7799033; New Holland: 8203048	FIAT: Tipo 2P/4P 1.6 8V (SPI - gasolina), Tempra 1.6ie 1993 / 1996
	GS8303 comprimento do cabo: 64cm	Bosch: 0 261 210 103, 0 261 210 118; Fiat: 7756924, 7799032	FIAT: Elba CSL 1.6 (MPI) Todos, Fiorino, Pick-up 1.6 (MPI) 95>96, Tempra 1.6ie 04/93>12/96, Tipo 1.6 ie (gasolina) c/ AC 93>95, Tipo 1.6 8V (MPI - gasolina) c/ AC 96>97, Uno 1.6 8V (MPI - gasolina) 95>96
	GS8305	Ford: 94BF-6C315-AA, 948F-6C315-AA, 92BF-6C315-A1F, 928F-6C315-A1F, F5RZC315AA;	Ford: Escort 91>, Fiesta 1.0, 1.4 95>, Focus 98>04, KA 1.3 96>08, Mondeo 96>00, Transit 00>06;
	GS8307	Fiat: 5033307AC	Fiat: Freemont 2.4; Dodge: Journey 2.0 / 2.4; Jeep: Compass 2.0 16V 2011>
	GS8315 comprimento do cabo: 99cm	Bosch: 0 261 210 030; GM: 90 213 515, 90 451 441; VDO: 324 003 007R	GM: Astra, Sedan 2.0 (MPFI) 09/94>12/96, Astra 2.0i 09/91>02/98, Astra, Sedan 2.0 (MPFI) 09/03>, Astra, Sedan 2.0 (MPFI - Flexpower) 04/04>, Blazer, S10 2.2 (MPFI) 08/97>04/00, Blazer, S10 2.4 (MPFI) 05/00>01/07, Calibra 2.0i/2.0i turbo 06/90>03/97, Calibra 2.0 16V 10/93>03/96, Omega, Suprema GLS 2.0 (MPFI) 09/92>12/95, Omega 1.8/1.8i/2.0i 09/86>03/94, Vectra 1.8i 03/90>08/95, Vectra CD 2.0 8V, Vectra GLS 2.0 (MPFI) 10/93>03/96, Vectra GSI 2.0 16V 10/93>03/96, Zafira 2.0 (MPFI - Flexpower) 03/04>
	GS8319 comprimento do cabo: 48cm	Bosch: 0 261 210 119; Fiat: 7790917	FIAT: Marea, Marea Weekend 2.0i 20V (Turbo) 05/98>
	GS8321	Jeep: 4897321AA, 56027865AC, 56027868, 56027868AB, 56027868AC, 56027869AC	JEOP: Jeep Grand Cherokee Laredo 4.0 1997>2004, Jeep Grand Cherokee Limited 4.0 1997>2004, Wrangler 4.0 Sport 4x4 1997>2007
	GS8324 comprimento do cabo: 61,5cm	Bosch: 0 261 210 124; Fiat: 77872650, 46774532, 55187333, 7777960	FIAT: Fiorino Furgão Fire 2P 1.3 8V (MPI - gasolina) 03/00>, Palio EX Fire 2P/4P 1.0 8V (MPI - gasolina) 01>03, Palio EX Fire 2P/4P 1.3 8V (MPI - gasolina) 03, Palio EX Fire Flex 2P 1.0 8V (MPI - álcool/gasolina) 06>, Palio ELX Fire Flex 4P 1.0 8V (MPI - álcool/gasolina) 06>, Palio ELX Fire Flex 4P 1.3 8V (MPI - álcool/gasolina) 04>05, Palio Fire 2P/4P 1.0 8V (MPI - gasolina) 03/00>04, Palio Fire Flex 2P/4P 1.0 8V (MPI - álcool/gasolina) 06>, Palio Penta Fire 4P 1.0 8V (MPI - gasolina) 03, Palio Weekend EX Fire 4P 1.3 8V (MPI - gasolina) 03>04, Palio Weekend ELX Fire Flex 4P 1.3 8V (MPI - álcool/gasolina) 05, Palio Young Fire 2P/4P 1.0 8V (MPI - gasolina) 02, Siena ELX Fire Flex 4P 1.0 8V (MPI - álcool/gasolina) 02>03 / 4P 1.3 8V (MPI - álcool/gasolina) 06>, Siena EX Fire 4P 1.3 8V (MPI - gasolina) 03>04, Siena Fire 4P 1.0 8V (MPI - gasolina) 05, Siena Fire Flex 4P 1.0 8V (MPI - álcool/gasolina) 06>, Strada Fire 2P 1.3 8V (MPI - gasolina) 03>05, Strada Fire estendida 2P 1.3 8V (MPI - gasolina) 03>05, Uno Furgoneta Fire 2P 1.3 8V (MPI - gasolina) 03>, Uno Mille Fire 2P/4P 1.0 8V (MPI - gasolina) 02>06, Uno Mille Fire Flex 2P/4P 1.0 8V (MPI - álcool/gasolina) 06>

FOTO	CÓD. GAUSS	SUBSTITUI	APLICAÇÃO
	GS8328 comprimento do cabo: 100cm	Bosch: 0 261 210 128; GM: 92062490, 93232413; VDO: 324003007R	GM: Astra, Sedan 1.8 (MPFI) 98 > , Astra, Sedan 2.0 (MPFI) 98>, Astra Sedan 2.0 (MPFI - Multipower) 04 >, Blazer, S10 2.4 (MPFI - Flexpower) 07 >, Vectra 2.0 (Flexpower) 05 > Vectra B 2.0 (MPFI) 96 / 98 e 03 / 05, 2.2 (MPFI) 98 > 02, Vectra C 2.0 Flex 05 > , Vectra Hatch 2.0 (Flexpower) 07 > , Zafira 2.0 (MPFI) 01 > 04
	GS8331 comprimento do cabo: 44cm sem ar-condicionado	Fiat: 46445731; Magneti Marelli: 4820171010	FIAT: Fiorino Furgão, Pick up 1.5 8V (MPI - álcool/gasolina) 97>04 / , Palio 1.5 8V (MPI - álcool) 96 > 00 e 03 > 04, Palio 1.0 8V MPI 96 > 00, Young 1.0 8V 01 > 02, Weekend 1.5 8V MPI 97 > 00 Weekend 1.0 8V MPI 99 > 00, Siena 1.5 8V MPI 99 > 00 e 03 > 04 , Strada 1.5 8V MPI 00 > 04, Uno, Mille, Furgoneta 1.5 8V MPI 97 > 04, Mille 1.6 8V MPI 99 > 04
	GS8332 comprimento do cabo: 73cm	Magneti Marelli: 1040211101; Fiat: 55187332, 55189515, 46479975	FIAT: Brava SX, ELX 4P 1.6 16V (MPI - gasolina) 00 > 03, Doblo Cargo 2P 1.6 16V (MPI - gasolina) 02 > 03 / ELX 2P 1.6 16V (MPI - gasolina) 02 > 03, Marea, Marea Weekend SX 4P 1.6 16V (MPI - gasolina) 06 > , Palio 1.6 16V (MPI - gasolina) 96 > 03 / 1.6 16V (MPI - gasolina) 96>00 / ELX 1.6 16V 01>03 / Stile 1.6 16V (MPI - gasolina) 01>02 / Adventure 1.6 16V (MPI - gasolina) 01>03 / Weekend 1.6 16V (MPI - gasolina) 97>98 / Weekend Sport 1.6 16V (MPI - gasolina) 97>00 / Weekend Stile 1.6 16V (MPI - gasolina) 97>03, Siena EL 1.6 16V (MPI - gasolina) 98 / ELX 1.6 16V (MPI - gasolina) 01>03 / HL 1.6 16V (MPI - gasolina) 98 / Sport MTV 1.6 16V (MPI - gasolina) 98 / Stile 1.6 16V (MPI - gasolina) 98>99, Strada LX 1.6 16V (MPI - gasolina) 99>00 / LX estendida 1.6 16V (MPI - gasolina) 00>02 / Working estendida 1.6 16V (MPI - gasolina) 01 / Working 1.6 16V (MPI - gasolina) 02 / Adventure 1.6 16V (MPI - gasolina) 02
	GS8337 comprimento do cabo: 21cm	Bosch: 0 261 210 137; Renault: 770085931 / 7702218699	RENAULT: Clio 1.6i 96 > 97, R19 Sedan 1.6i 93 > 00
	GS8339 comprimento do cabo: 88,5cm chicote longo	GM: 90 483 739; Bosch: 0 261 210 048	GM: Corsa, GSI, Sedan, Wagon 1.0 , 1.6 16V 97 > 02, Corsa 1.6 8V 95>01, Tigra 1.6 16V 96 >
	GS8341	Bosch: 0 986 280 403; Renault: 7700720341, 7700725811, 7700728639, 7700732300, 7700739792	RENAULT: 11 1.4/ 1.7 1985>1995, 9 1.4 1988>1995, Clio 1.2/ 1.4/ 1.7 1990>1998, Espace I 2.0 8V 1988>1990, Express 1.2 8V/ 1.4 8V 1985>, R19 1.2/ 1.4/ 1.7 1989>, R21 1.4/ 1.6/ 1.7 1986>1994, R25 2.0/ 2.2 8V 1984>1992, Trafic 1.7 8V 1992>1994
	GS8342 comprimento do cabo: 66cm	GM: 90 451 442; VDO: 324003001R	GM: Astra 1.8 16V 03>, Celta 1.0/1.4 (MPFI) 01>, Corsa 1.4/1.6 (EFI - MPFI) 95>, Corsa 1.0/1.4/1.6 (MPFI - gasolina/Flexpower) 02>, Corsa 1.8 (MPFI - gasolina) 04>, Meriva 1.8 8V (MPFI - gasolina/Flexpower) 03>, Montana 1.8 8V (MPFI - gasolina/Flexpower) 04>
	GS8348 comprimento do cabo: 58cm	Bosch: 0 261 210 147, 0 261 210 148 ; VW: 06A906433C	AUDI: A3 1.6, 1.8, 1.8 20V Turbo 96 / 06, A4, A6, A8, TT 1.8T; VW: Bora 1.6 , 1.8 , 2.0 98 / 06, Golf IV 1.6 97 / 04, 1.8 T 97 / 08, Jetta 98 / 05 , New Beetle 2.0 98 / 05 , Passat 00 / 05 , Polo Classic 99 / 01
	GS8350 comprimento do cabo: 83cm	Bosch: 0 261 210 150; GM 93243251, 90510656	GM: Astra 2.0i (SFI)16V 99>05 / 2.0 GTC Turbo 05> / Turbo / Cabrio 02>05, Astra Sedan 2.0 (SFI) 16V 99>04, Vectra 2.2i 16V (SFI) 97>05, Vectra CD 2.0 16V (SFI) 96>97, Zafira 2.0 16V (SFI) 01>05
	GS8360 comprimento do cabo: 62cm	Bosch: 0 261 210 160 ; Fiat: 46470477, 46469866, 46472687, 60814589	ALFA ROMEO: Alfa 146 1.8/2.0 TS 16V 98 > 00, Alfa 147 1.6/2.0 TS 16V 00 >, Alfa 156 SW 2.0 TS 16V 97 > 05, Spider 98 /06 , Alfa 166 98 >; FIAT: Coupé 98 / 00, Marea, Marea Weekend 2.0 , 2.4i 20V Turbo 00 >, Stilo 2.4 (MPI) 20V 01 >

FOTO	CÓD. GAUSS	SUBSTITUI	APLICAÇÃO
	GS8361 comprimento do cabo: 66cm	Bosch: 0 261 210 161, 0 261 210 219; Fiat: 46474583, 46754538, 46754539	FIAT: Doblo 1.3 (MPI) 16V 01 > 06, Palio 1.0 16V, 1.3 16V (Fire) 00 > 03, Palio Weekend 1.0 16V, 1.3 (Fire) 00 > 03, Siena 1.0 16V, 1.3 16V (Fire) 00 > 03, Strada 1.3 16V (Fire) 00 >
	GS8383 comprimento do cabo: 33cm	Bosch: 0 261 210 043, 0 261 210 065, 0 261 210 083, 0 261 210 154; Hyundai: 3918022001; KIA: 0K04G-18-891, 0K934-18-891	GM: Omega, Suprema CD 4.1(MPFI) 10/94>12/98, Pick-up C20 (MPFI) 02/92>12/96, Silverado 4.1(MPFI) 01/96>09/97; HYUNDAI: Scoupe 1.5/1.5i/GTi 1.5i Turbo 02/90>04/95; KIA: Sportage 2.0i 16V 4WD FE (16V) 04/94>, Sportage 2.0i 4WD FE 04/94>08/99, Sportage 2.2i 04/94>12/97
	GS8384 * Saída para o lado esquerdo	Renault: 7700101969, 7700875184B, 8200436025; Bosch: 0 986 280 411	RENAULT: Clio 1.0 8V 99>, Clio II 1.0 8V, 16V 99>02, Kangoo 1.0 8V/16V 98>, Kangoo 1.6 8V 00>, Scenic 1.6i 96>03, Twingo 1.0 16V 01>07
	GS8389 comprimento do cabo: 85cm	GM: 90 508 637, 93 384 389; VDO: 324003008R	GM: Astra, Zafira 2.0L 16V 03>09, Astra, Zafira 2.4L 16V 04>09, Vectra B 16V 97>, Vectra C 2.4 16V 06>
	GS8391 comprimento do cabo: 61cm	Fiat: 7 083 327, 7 083 791; GM: 93 393 867; VDO: 324003002	FIAT: Doblo, Idea, Palio, Siena, Stilo, Strada, Weekend 1.8 8V 04>; GM: Corsa, Meriva, Montana 1.8 8V (MPFI - Flexpower) 04>
	GS8405	Bosch: 0.986.280.405; Renault: 7700855719, 7700728637, 7700739794, 7700748442;	Renault: Mégane 1.4/ 1.6 95>, Laguna 93>01, Espace 96>, Twingo 1.2 93>98
	GS8427	Dodge / Jeep: 4713427, 56026882, 56027031, 56029621	JEEP: Cherokee 4.0 i 4x4 1999>2001; DODGE: Dakota 2.5 1995>2003
	GS8433	VW: 032.906.433, 03C.906.433A	VW: Gol, Fox 1.0/ 1.6, Polo 1.6, Golf 1.6, Kombi 1.4, Passat 05>, Jetta 05>, Beetle 11>; Audi: Audi TT 06>, A3, A4, A5 2007>
	GS8450	Chevrolet: 12498965, 10456118; Meat & Doria: 87233; Mobiletron: CS-K007	CHEVROLET: Blazer 2.2/2.4 1995>2000, Omega 2.2 MPFI 1995>1998, S10 2.0 EFI 1995>2000, Suprema 2.2 1995>1998 (todos 4Cil e 8V)
	GS8471	Mitsubishi: J5T38471; Honda: 37510-59BJ01	HONDA: Civic Touring CVT 1.5 Turbo 2017>
	GS8500	Hyundai: 39180-23500; Kia: 39180-23910	Hyundai: Tucson 2.0 16V 2005>2009, Elantra 1.6/ 1.8/ 2.0 2006>, i30 2.0 2007>; Kia: Sportage 2005>2009, Soul 2010, Cerato 2.0 2006>

FOTO	CÓD. GAUSS	SUBSTITUI	APLICAÇÃO
	GS8513	Bosch: 0 281 002 513; Iveco: 500374763	IVECO: Daily 40 S 16 2007>, Daily 45 S 14/16 2007> Daily 55 C 16 2007>, Daily 70 C 16 / HD Massimo 2010>, Daily 2000 35 S 14 2007>
	GS8542	GM: 96253542, 96434780; Delphi: SS10894; Magneti Marelli: 064848106010	DAEWOO: Nubira 1.6 1997>2004, Nubira 1.4 2003>2004
	GS8556	Nissan: 01436-00QAC, 23750-00QAG, 23750-00QOE; Renault: 7700108073, 8200468647, 8200647556	Nissan: Kubistar 1.6 16V 2003>; Renault: Clio 1.4 16V 1999>2004, Clio 1.6 16V 1998>, Espace 2.0 16V 1998>2002, Kangoo 1.6 2001>
	GS8571	Mitsubishi: J5T32571, 1865A069	Mitsubishi: Lancer 2008>2011, Outlander 3.0 2008>2011, Outlander Sport 2011
	GS8600	Hyundai/Kia: 39650-42600	Hyundai: H100 2004>; Kia: Bongo
	GS8622	Mitsubishi: MD320622, J5T25082A, PC96	MITSUBISHI: Pajero Sport 3.0 1998>, Pajero Full 3.5, L200 2.5 1997>2011
	GS8643	VW: 041906433A; VDO: 340215002R	VW: Gol GL 2003>2006, Gol GL 2006>2010, Gol G4 2011>2014, Saveiro 2006>2010, Parati 1.6 2011>2013, Fox, Voyage, Golf, Polo, Spacefox (todos com motor AP)
	GS8700	Hyundai: 39310-02700 / 39310-02600	Hyundai: Atos 1.0/1.1 2001>2007, Atos Prime; Kia: Picanto 1.0/1.1 2001>2003
	GS8712	GM: 12567712	GM: Malibu 2.4 2010>2015
	GS8780	Citroën / Peugeot: 9640627780, 1920FP, 1920EN; Suzuki: 33220-67G01-000	Citroën: C4, C5, C6, Xsara Picasso 2006>; Peugeot: 307, 407 2005>; Suzuki: Gran Vitara
	GS8795	GM: 90412795; Opel: 6238000	GM: Corsa 1.0/ 1.6 16V 93>03, Tigra 1.6 94>

FOTO	CÓD. GAUSS	SUBSTITUI	APLICAÇÃO
	GS8826	Mitsubishi: MD342826, J5T25871, ADC47205	Mitsubishi: Pajero 2.5 GLX 1990>1999, Pajero 2.5 TDI Sport 2001>2007, L200 2.5 TD 1987>1992, L200 2.5 TD GL/GLS 1996>2007, Montero 3.5 V6 1994>2000, Montero Sport 3.0 V6 1997>2004
	GS8865	Fiat: 55261865	FIAT: Argo HGT 1.8 2017>
	GS8880	Citroën / Peugeot: 9639999880, 9637465980 1920AW; Bosch: 0.986.280.408; Delphi: SS10747-12B1	Citroën: Aircross 1.6 10>, C2 1.6 04>09, C3 1.4/ 1.6 03>, C4 09>, Hoggar 1.4/ 1.6 10>, Xsara 1.6 00>06; Peugeot: 206 1.4/ 1.6 Flex All, 207 1.4/ 1.6 08>13, 307 1.6 00>
	GS8920	Citroën / Peugeot: 9639999980, 1920AV; Delphi: SS10748-12B1	Peugeot: 206 1.4/ 1.6, 306 1.6; Citroën: C3 1.4/1.6, C4 1.4/1.6, Xsara Picasso 1.6
	GS8991	GM: 12590991; Bosch: 0 261 210 274	GM: Captiva 3.0/3.6 V6 2008>, Malibu, Omega Australiano 1999>2005
	GS8992	GM: 12588992	Chevrolet: Agile, Montana, Onix, Prisma, Captiva 2.4 2006, Malibu 2.4 2012